Lessons Learned from the Field

H.Q. Construction Office

Report


April 2005

Verifying Elevations for Constructability and Design




















I-90 Tibbetts Creek



Drilled Shaft/Geotechnical Issues







SR18 Maple Valley – Taylor 2 WB

LOG OF TEST BORING

lob No


OL-3112

. 18

HOLE No. TCA-7-02

PROJECT _ Maple Valley to Issaquah Hobart rd.

Sheet 3 of 4




Tall Abutment Walls Backfill Isolation





Seismic Retrofit Details and Specifications



"Varies" is not adequately descriptive

Recommendation

- Provide approx. dimensions
- Give estimated elevations
- Require Contractor to fieldverify


North Seattle Bridges - Seismic



Issues with seismic retrofit field measuring

- Make lump-sum payment
 - Not incidental to seismic work
 - Not a payment per each
- Specify that results are to be incorporated into shop drawings.

Expansion Jt. Retrofit









Falsework Clearances













Reinforcing Congestion







Lack of Room For Shoring Between Stages



Bearing Grout Pads







Long Span Tub Girder Bridges




Screen Drain Holes








Details







CRIP

- Pre-conceptual Structural Evaluation
- Short Review Time
- Merit Evaluation

Traffic Restrictions During Deck Closure Placement

Evaluate for:

- Vibration From Adjacent Traffic
- Long Span Live Load Deflection

Shaft Construction Report

- Shafts constructed = 140
- Shafts with defects = 19
- Shafts repaired = 2
- Shafts rejected = 1
- FA paid / FA estimated = 16%
- Claims = \$115K

Post-tensioned Duct Void Detection







